


City of Fairhope – Outfall Inventory Stack Gully Watershed


SG-12773-A

SG-12773-A
✖



IMG_0027366.jpg

COF MS4 ID	SG-12773-A
Watershed	Stack Gully
Material	PVC
Shape_1	Circular
Depth	0
Top Width	0
Bottom Width	0
Type	Closed Pipe
Category	
Outfall_No	<Null>
Comment	
Flow Description	
Outfall Damage	
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	1
Diameter	32
Submerged in Water	No
Submerged With Sediment	No
Date Collected	7/9/2012
2012 Photo 1	0027366
2012 Photo 2	<Null>



MORPHY AV
SUMMIT ST
CHURCH ST
FELS AV

City of Fairhope - Outfall Inventory Stack Gully Watershed

SG-12788-A


IMG_00004.jpg

COF MS4 ID	SG-12788-A
Watershed	Stack Gully
Material	RCP
Shape_1	Circular
Depth	0
Top Width	0
Bottom Width	0
Type	Closed Pipe
Category	Major Bay Outfall
Outfall_No	11
Comment	
Flow Description	Trickle
Outfall Damage	Spalling_Cracking_Ch
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	Green
Barrels	1
Diameter	36
Submerged in Water	No
Submerged With Sediment	No
Date Collected	6/14/2012
2012 Photo 1	00004
2012 Photo 2	<Null>

City of Fairhope - Outfall Inventory Stack Gully Watershed


SG-12795-A ✖

SG-12795-A



IMG_0019306.jpg

COF MS4 ID	SG-12795-A
Watershed	Stack Gully
Material	HDPE
Shape_1	Circular
Depth	0
Top Width	0
Bottom Width	0
Type	Closed Pipe
Category	Bay Outfall
Outfall_No	3
Comment	Bay outfall
Flow Description	None
Outfall Damage	
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	1
Diameter	24
Submerged in Water	No
Submerged With Sediment	No
Date Collected	7/3/2012
2012 Photo 1	0019306
2012 Photo 2	<Null>



City of Fairhope – Outfall Inventory Stack Gully Watershed

SG-12795-B

SG-12795-B

IMG_0019307.jpg

COF MS4 ID	SG-12795-B
Watershed	Stack Gully
Material	HDPE
Shape_1	Circular
Depth	0
Top Width	0
Bottom Width	0
Type	Closed Pipe
Category	Bay Outfall
Outfall_No	4
Comment	Bay outfall
Flow Description	Trickle
Outfall Damage	
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	1
Diameter	24
Submerged in Water	Partially
Submerged With Sediment	No
Date Collected	7/3/2012
2012 Photo 1	0019307
2012 Photo 2	<Null>

City of Fairhope - Outfall Inventory Stack Gully Watershed

SG-12795-C

SG-12795-C

IMG_0019308.jpg

COF MS4 ID	SG-12795-C
Watershed	Stack Gully
Material	HDPE
Shape_1	Circular
Depth	0
Top Width	0
Bottom Width	0
Type	Closed Pipe
Category	Bay Outfall
Outfall_No	5
Comment	Bay outfall
Flow Description	None
Outfall Damage	
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	1
Diameter	24
Submerged in Water	No
Submerged With Sediment	No
Date Collected	7/3/2012
2012 Photo 1	0019308
2012 Photo 2	<Null>

City of Fairhope - Outfall Inventory Stack Gully Watershed

SG-1728-A

SG-1728-A

IMG_0027365.jpg

COF MS4 ID	SG-1728-A
Watershed	Stack Gully
Material	CMP
Shape_1	Circular
Depth	0
Top Width	0
Bottom Width	0
Type	Closed Pipe
Category	
Outfall_No	<Null>
Comment	From Cliff Drive
Flow Description	None
Outfall Damage	
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	1
Diameter	24
Submerged in Water	No
Submerged With Sediment	Partially
Date Collected	7/9/2012
2012 Photo 1	0027365
2012 Photo 2	<Null>

City of Fairhope - Outfall Inventory Stack Gully Watershed

SG-19592-A

SG-19592-A


IMG_0027367.jpg

COF MS4 ID	SG-19592-A
Watershed	Stack Gully
Material	CMP
Shape_1	Circular
Depth	0
Top Width	0
Bottom Width	0
Type	Closed Pipe
Category	
Outfall_No	<Null>
Comment	Eroded severe below pipe discharge
Flow Description	None
Outfall Damage	
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	1
Diameter	15
Submerged in Water	No
Submerged With Sediment	No
Date Collected	7/9/2012
2012 Photo 1	0027367
2012 Photo 2	<Null>

City of Fairhope - Outfall Inventory Stack Gully Watershed

SG-64356-A


SG-64356-A



IMG_0027371.jpg

[IMG_0027371.jpg](#) [IMG_0028372.jpg](#)

COF MS4 ID	SG-64356-A
Watershed	Stack Gully
Material	Rip_rap
Shape_1	Other
Depth	0
Top Width	0
Bottom Width	0
Type	Open Drainage
Category	
Outfall_No	<Null>
Comment	Armored ditch checkdam gabion sidewall
Flow Description	None
Outfall Damage	
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	
Diameter	0
Submerged in Water	
Submerged With Sediment	
Date Collected	7/9/2012
2012 Photo 1	0027371
2012 Photo 2	0028372



City of Fairhope - Outfall Inventory Stack Gully Watershed

SG-64356-B

SG-64356-B


IMG_0027373.jpg

COF MS4 ID	SG-64356-B
Watershed	Stack Gully
Material	Rip_rap
Shape_1	Other
Depth	0
Top Width	0
Bottom Width	0
Type	Open Drainage
Category	
Outfall_No	<Null>
Comment	Gabion sidewall
Flow Description	None
Outfall Damage	
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	
Diameter	0
Submerged in Water	
Submerged With Sediment	
Date Collected	7/9/2012
2012 Photo 1	0027373
2012 Photo 2	<Null>

City of Fairhope - Outfall Inventory Stack Gully Watershed


SG-64356-C

SG-64356-C



IMG_0028376.jpg


COF MS4 ID	SG-64356-C
Watershed	Stack Gully
Material	Rip_rap
Shape_1	Other
Depth	0
Top Width	0
Bottom Width	0
Type	Open Drainage
Category	
Outfall_No	<Null>
Comment	Gabion sidewall beginning
Flow Description	
Outfall Damage	
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	
Diameter	0
Submerged in Water	
Submerged With Sediment	
Date Collected	7/9/2012
2012 Photo 1	0028376
2012 Photo 2	<Null>



City of Fairhope – Outfall Inventory Stack Gully Watershed


SG-64356-D

SG-64356-D



IMG_0028377.jpg


COF MS4 ID	SG-64356-D
Watershed	Stack Gully
Material	Rip_rap
Shape_1	Other
Depth	0
Top Width	0
Bottom Width	0
Type	Open Drainage
Category	
Outfall_No	<Null>
Comment	Gabion sidewall end of
Flow Description	
Outfall Damage	
Deposits/Stains	Flow_line
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	
Diameter	0
Submerged in Water	
Submerged With Sediment	
Date Collected	7/9/2012
2012 Photo 1	0028377
2012 Photo 2	<Null>



City of Fairhope - Outfall Inventory Stack Gully Watershed

SG-64356-E

SG-64356-E



IMG_0028382.jpg

COF MS4 ID	SG-64356-E
Watershed	Stack Gully
Material	HDPE
Shape_1	Circular
Depth	0
Top Width	0
Bottom Width	0
Type	Closed Pipe
Category	
Outfall_No	<Null>
Comment	Into drop structure
Flow Description	None
Outfall Damage	
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	1
Diameter	12
Submerged in Water	No
Submerged With Sediment	No
Date Collected	7/9/2012
2012 Photo 1	0028382
2012 Photo 2	<Null>

City of Fairhope - Outfall Inventory Stack Gully Watershed

SG-64356-F

SG-64356-F




IMG_0028381.jpg

COF MS4 ID	SG-64356-F
Watershed	Stack Gully
Material	CMP
Shape_1	Circular
Depth	0
Top Width	0
Bottom Width	0
Type	Closed Pipe
Category	
Outfall_No	<Null>
Comment	Into drop structure
Flow Description	
Outfall Damage	
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	1
Diameter	15
Submerged in Water	No
Submerged With Sediment	No
Date Collected	7/9/2012
2012 Photo 1	0028381
2012 Photo 2	<Null>

City of Fairhope - Outfall Inventory Stack Gully Watershed

SG-64356-G

SG-64356-G




IMG_0028380.jpg

COF MS4 ID	SG-64356-G
Watershed	Stack Gully
Material	RCP
Shape_1	Circular
Depth	0
Top Width	0
Bottom Width	0
Type	Closed Pipe
Category	
Outfall_No	<Null>
Comment	Into drop structure
Flow Description	None
Outfall Damage	
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	1
Diameter	24
Submerged in Water	No
Submerged With Sediment	No
Date Collected	7/9/2012
2012 Photo 1	0028380
2012 Photo 2	<Null>

City of Fairhope - Outfall Inventory Stack Gully Watershed

The image shows an aerial view of a residential neighborhood with property lines overlaid in pink. A specific location is marked with a cyan dot, and a callout window provides a close-up photograph of a closed pipe and a table of associated data.

SG-64356-H	
SG-64356-H	
	
IMG_0027368.jpg	
IMG_0027368.jpg	IMG_0028369.jpg
COF MS4 ID	SG-64356-H
Watershed	Stack Gully
Material	CMP
Shape_1	Circular
Depth	0
Top Width	0
Bottom Width	0
Type	Closed Pipe
Category	
Outfall_No	<Null>
Comment	
Flow Description	None
Outfall Damage	
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	1
Diameter	18
Submerged in Water	No
Submerged With Sediment	No
Date Collected	7/9/2012
2012 Photo 1	0027368
2012 Photo 2	0028369

City of Fairhope - Outfall Inventory Stack Gully Watershed

SG-64356-I

SG-64356-I

IMG_0027370.jpg

COF MS4 ID	SG-64356-I
Watershed	Stack Gully
Material	CMP
Shape_1	Circular
Depth	0
Top Width	0
Bottom Width	0
Type	Closed Pipe
Category	
Outfall_No	<Null>
Comment	Concrete lined pipe
Flow Description	None
Outfall Damage	
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	1
Diameter	38
Submerged in Water	No
Submerged With Sediment	No
Date Collected	7/9/2012
2012 Photo 1	0027370
2012 Photo 2	<Null>

City of Fairhope - Outfall Inventory Stack Gully Watershed

SG-64356-J

SG-64356-J


IMG_0028374.jpg

[IMG_0028374.jpg](#) [IMG_0029375.jpg](#)

COF MS4 ID	SG-64356-J
Watershed	Stack Gully
Material	CMP
Shape_1	Circular
Depth	0
Top Width	0
Bottom Width	0
Type	Closed Pipe
Category	
Outfall_No	<Null>
Comment	Concrete lined pipe
Flow Description	None
Outfall Damage	
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	1
Diameter	42
Submerged in Water	No
Submerged With Sediment	No
Date Collected	7/9/2012
2012 Photo 1	0028374
2012 Photo 2	0029375

City of Fairhope - Outfall Inventory Stack Gully Watershed


The popup window displays the following information:

SG-64362-A	
SG-64362-A	
	
IMG_0028378.jpg	
COF MS4 ID	SG-64362-A
Watershed	Stack Gully
Material	CMP
Shape_1	Circular
Depth	0
Top Width	0
Bottom Width	0
Type	Closed Pipe
Category	
Outfall_No	<Null>
Comment	Under Scenic 98
Flow Description	None
Outfall Damage	Corrosion
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	2
Diameter	60
Submerged in Water	No
Submerged With Sediment	No
Date Collected	7/9/2012
2012 Photo 1	0028378
2012 Photo 2	<Null>

City of Fairhope - Outfall Inventory Stack Gully Watershed

SG-64362-B

SG-64362-B



IMG_0028379.jpg

COF MS4 ID	SG-64362-B
Watershed	Stack Gully
Material	CMP
Shape_1	Circular
Depth	0
Top Width	0
Bottom Width	0
Type	Closed Pipe
Category	
Outfall_No	<Null>
Comment	Corroded invert
Flow Description	None
Outfall Damage	Corrosion
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	1
Diameter	24
Submerged in Water	No
Submerged With Sediment	No
Date Collected	7/9/2012
2012 Photo 1	0028379
2012 Photo 2	<Null>

City of Fairhope - Outfall Inventory Stack Gully Watershed

SG-64362-C

SG-64362-C


IMG_00003.jpg

COF MS4 ID	SG-64362-C
Watershed	Stack Gully
Material	RCP
Shape_1	Arch
Depth	0
Top Width	0
Bottom Width	0
Type	Closed Pipe
Category	
Outfall_No	<Null>
Comment	
Flow Description	None
Outfall Damage	
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	1
Diameter	0
Submerged in Water	No
Submerged With Sediment	No
Date Collected	6/14/2012
2012 Photo 1	00003
2012 Photo 2	<Null>

City of Fairhope - Outfall Inventory Stack Gully Watershed

SG-64362-D

SG-64362-D



IMG_00002.jpg

COF MS4 ID	SG-64362-D
Watershed	Stack Gully
Material	RCP
Shape_1	Circular
Depth	0
Top Width	0
Bottom Width	0
Type	Closed Pipe
Category	
Outfall_No	
Comment	
Flow Description	Moderate
Outfall Damage	
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	1
Diameter	15
Submerged in Water	No
Submerged With Sediment	No
Date Collected	6/14/2012
2012 Photo 1	00002
2012 Photo 2	<Null>

City of Fairhope - Outfall Inventory Stack Gully Watershed

SG-64362-E

SG-64362-E

IMG_00001.jpg

COF MS4 ID	SG-64362-E
Watershed	Stack Gully
Material	HDPE
Shape_1	Circular
Depth	0
Top Width	0
Bottom Width	0
Type	Closed Pipe
Category	Major Bay Outfall
Outfall_No	12
Comment	
Flow Description	Trickle
Outfall Damage	Spalling_Cracking_Ch
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	2
Diameter	42
Submerged in Water	No
Submerged With Sediment	No
Date Collected	6/14/2012
2012 Photo 1	00001
2012 Photo 2	<Null>

City of Fairhope - Outfall Inventory Stack Gully Watershed

SG-64364-A

SG-64364-A

IMG_0019309.jpg

COF MS4 ID	SG-64364-A
Watershed	Stack Gully
Material	Concrete
Shape_1	Trapezoid
Depth	2
Top Width	6
Bottom Width	2
Type	Open Drainage
Category	Bay Outfall
Outfall_No	8
Comment	Bay outfall
Flow Description	None
Outfall Damage	
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	
Diameter	0
Submerged in Water	
Submerged With Sediment	
Date Collected	7/3/2012
2012 Photo 1	0019309
2012 Photo 2	<Null>