


City of Fairhope - Outfall Inventory Volanta Watershed

VL-110128-A



IMG_0027355.jpg

[IMG_0027355.jpg](#)
[IMG_0028356.jpg](#)

COF MS4 ID	VL-110128-A
Watershed	Volanta
Material	CMP
Shape_1	Circular
Depth	0
Top Width	0
Bottom Width	0
Type	Closed Pipe
Category	
Outfall_No	<Null>
Comment	Big erosion below pipe discharge
Flow Description	Trickle
Outfall Damage	Corrosion
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	1
Diameter	24
Submerged in Water	No
Submerged With Sediment	No
Date Collected	7/6/2012
2012 Photo 1	0027355
2012 Photo 2	0028356

City of Fairhope - Outfall Inventory Volanta Watershed

VL-18772-A

VL-18772-A


IMG_0015205.jpg

IMG_0015205.jpg	IMG_0016206.jpg
COF MS4 ID	VL-18772-A
Watershed	Volanta
Material	RCP
Shape_1	Circular
Depth	0
Top Width	0
Bottom Width	0
Type	Closed Pipe
Category	
Outfall_No	<Null>
Comment	Eroded severe downstream
Flow Description	None
Outfall Damage	
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	1
Diameter	36
Submerged in Water	No
Submerged With Sediment	Partially
Date Collected	7/2/2012
2012 Photo 1	0015205
2012 Photo 2	0016206

City of Fairhope - Outfall Inventory Volanta Watershed

VL-18772-B

VL-18772-B




IMG_0015207.jpg

COF MS4 ID	VL-18772-B
Watershed	Volanta
Material	Earthen
Shape_1	Other
Depth	8
Top Width	15
Bottom Width	4
Type	Open Drainage
Category	
Outfall_No	<Null>
Comment	Mobile Street discharge to Volanta Gully
Flow Description	None
Outfall Damage	
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	
Diameter	0
Submerged in Water	
Submerged With Sediment	
Date Collected	7/2/2012
2012 Photo 1	0015207
2012 Photo 2	<Null>

City of Fairhope - Outfall Inventory Volanta Watershed

VL-18772-C

VL-18772-C



IMG_0015208.jpg

COF MS4 ID	VL-18772-C
Watershed	Volanta
Material	Earthen
Shape_1	Other
Depth	2
Top Width	6
Bottom Width	2
Type	Open Drainage
Category	
Outfall_No	<Null>
Comment	Yard drainage
Flow Description	None
Outfall Damage	
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	
Diameter	0
Submerged in Water	
Submerged With Sediment	
Date Collected	7/2/2012
2012 Photo 1	0015208
2012 Photo 2	<Null>

City of Fairhope - Outfall Inventory Volanta Watershed

VL-33279-A

VL-33279-A

IMG_0027348.jpg

COF MS4 ID	VL-33279-A
Watershed	Volanta
Material	Other
Shape_1	Other
Depth	3
Top Width	4
Bottom Width	4
Type	Open Drainage
Category	
Outfall_No	<Null>
Comment	Sluice gate?
Flow Description	Trickle
Outfall Damage	
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	
Diameter	0
Submerged in Water	
Submerged With Sediment	
Date Collected	7/6/2012
2012 Photo 1	0027348
2012 Photo 2	<Null>

City of Fairhope - Outfall Inventory Volanta Watershed

VL-34073-A

VL-34073-A


IMG_0023339.jpg

COF MS4 ID	VL-34073-A
Watershed	Volanta
Material	CMP
Shape_1	Circular
Depth	0
Top Width	0
Bottom Width	0
Type	Closed Pipe
Category	
Outfall_No	<Null>
Comment	Jasmin Park
Flow Description	None
Outfall Damage	
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	1
Diameter	18
Submerged in Water	No
Submerged With Sediment	Partially
Date Collected	7/6/2012
2012 Photo 1	0023339
2012 Photo 2	<Null>

City of Fairhope - Outfall Inventory Volanta Watershed

VL-34073-B

VL-34073-B




IMG_0024340.jpg

COF MS4 ID	VL-34073-B
Watershed	Volanta
Material	CMP
Shape_1	Circular
Depth	0
Top Width	0
Bottom Width	0
Type	Closed Pipe
Category	
Outfall_No	<Null>
Comment	Ingleside crossing
Flow Description	Moderate
Outfall Damage	
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	1
Diameter	42
Submerged in Water	Partially
Submerged With Sediment	No
Date Collected	7/6/2012
2012 Photo 1	0024340
2012 Photo 2	<Null>

City of Fairhope - Outfall Inventory Volanta Watershed


VL-34073-C



IMG_0026344.jpg

COF MS4 ID	VL-34073-C
Watershed	Volanta
Material	HDPE
Shape_1	Circular
Depth	0
Top Width	0
Bottom Width	0
Type	Closed Pipe
Category	
Outfall_No	<Null>
Comment	Yard drainage ?
Flow Description	
Outfall Damage	
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	1
Diameter	24
Submerged in Water	No
Submerged With Sediment	No
Date Collected	7/6/2012
2012 Photo 1	0026344
2012 Photo 2	<Null>

City of Fairhope - Outfall Inventory Volanta Watershed




VL-34073-D

VL-34073-D

IMG_0026345.jpg

COF MS4 ID	VL-34073-D
Watershed	Volanta
Material	RCP
Shape_1	Circular
Depth	0
Top Width	0
Bottom Width	0
Type	Closed Pipe
Category	
Outfall_No	<Null>
Comment	Outfall
Flow Description	None
Outfall Damage	
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	1
Diameter	15
Submerged in Water	Fully
Submerged With Sediment	Fully
Date Collected	7/6/2012
2012 Photo 1	0026345
2012 Photo 2	<Null>

City of Fairhope - Outfall Inventory Volanta Watershed



VL-34073-E


VL-34073-E

IMG_0026346.jpg

COF MS4 ID	VL-34073-E
Watershed	Volanta
Material	RCP
Shape_1	Circular
Depth	0
Top Width	0
Bottom Width	0
Type	Closed Pipe
Category	
Outfall_No	<Null>
Comment	
Flow Description	None
Outfall Damage	
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	1
Diameter	15
Submerged in Water	Fully
Submerged With Sediment	Partially
Date Collected	7/6/2012
2012 Photo 1	0026346
2012 Photo 2	<Null>

City of Fairhope - Outfall Inventory Volanta Watershed


VL-36204-A




IMG_0027349.jpg

COF MS4 ID	VL-36204-A
Watershed	Volanta
Material	PVC
Shape_1	Circular
Depth	0
Top Width	0
Bottom Width	0
Type	Closed Pipe
Category	
Outfall_No	<Null>
Comment	Sewer line with hole
Flow Description	None
Outfall Damage	
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	1
Diameter	4
Submerged in Water	
Submerged With Sediment	
Date Collected	7/6/2012
2012 Photo 1	0027349
2012 Photo 2	<Null>

City of Fairhope - Outfall Inventory Volanta Watershed

VL-36204-B	
VL-36204-B	
	
IMG_0027347.jpg	
COF MS4 ID	VL-36204-B
Watershed	Volanta
Material	Rip_rap
Shape_1	Other
Depth	0
Top Width	0
Bottom Width	0
Type	Open Drainage
Category	
Outfall_No	<Null>
Comment	Checkdam
Flow Description	None
Outfall Damage	
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	
Diameter	0
Submerged in Water	
Submerged With Sediment	
Date Collected	7/6/2012
2012 Photo 1	0027347
2012 Photo 2	<Null>

City of Fairhope - Outfall Inventory Volanta Watershed




VL-43433-A

VL-43433-A

IMG_0027350.jpg

COF MS4 ID	VL-43433-A
Watershed	Volanta
Material	RCP
Shape_1	Circular
Depth	0
Top Width	0
Bottom Width	0
Type	Closed Pipe
Category	
Outfall_No	<Null>
Comment	From road crossing
Flow Description	None
Outfall Damage	
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	1
Diameter	36
Submerged in Water	Partially
Submerged With Sediment	No
Date Collected	7/6/2012
2012 Photo 1	0027350
2012 Photo 2	<Null>


City of Fairhope - Outfall Inventory Volanta Watershed

VL-43887-A	
VL-43887-A	
	
IMG_0015203.jpg	
IMG_0015203.jpg	IMG_0016204.jpg
COF MS4 ID	VL-43887-A
Watershed	Volanta
Material	Earthen
Shape_1	Trapezoid
Depth	4
Top Width	20
Bottom Width	12
Type	Open Drainage
Category	Bay Outfall
Outfall_No	10
Comment	Volanta Gulley discharge to Bay
Flow Description	Trickle
Outfall Damage	
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	
Diameter	0
Submerged in Water	
Submerged With Sediment	
Date Collected	7/2/2012
2012 Photo 1	0015203
2012 Photo 2	0016204

City of Fairhope - Outfall Inventory Volanta Watershed

VL-43889-A

VL-43889-A




IMG_0015210.jpg

COF MS4 ID	VL-43889-A
Watershed	Volanta
Material	CMP
Shape_1	Circular
Depth	0
Top Width	0
Bottom Width	0
Type	Closed Pipe
Category	
Outfall_No	<Null>
Comment	
Flow Description	
Outfall Damage	
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	1
Diameter	18
Submerged in Water	No
Submerged With Sediment	No
Date Collected	7/2/2012
2012 Photo 1	0015210
2012 Photo 2	<Null>

City of Fairhope - Outfall Inventory Volanta Watershed

VL-43889-B

VL-43889-B




IMG_0015211.jpg

COF MS4 ID	VL-43889-B
Watershed	Volanta
Material	Rip_rap
Shape_1	Other
Depth	6
Top Width	15
Bottom Width	5
Type	Open Drainage
Category	
Outfall_No	<Null>
Comment	Yard drainage
Flow Description	None
Outfall Damage	
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	
Diameter	0
Submerged in Water	
Submerged With Sediment	
Date Collected	7/2/2012
2012 Photo 1	0015211
2012 Photo 2	<Null>

City of Fairhope - Outfall Inventory Volanta Watershed

VL-43889-C

VL-43889-C




IMG_0015209.jpg

COF MS4 ID	VL-43889-C
Watershed	Volanta
Material	Earthen
Shape_1	Other
Depth	6
Top Width	10
Bottom Width	2
Type	Open Drainage
Category	
Outfall_No	<Null>
Comment	Below pipe discharge to Volanta Gulley
Flow Description	None
Outfall Damage	
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	
Diameter	0
Submerged in Water	
Submerged With Sediment	
Date Collected	7/2/2012
2012 Photo 1	<Null>
2012 Photo 2	0015209

City of Fairhope - Outfall Inventory Volanta Watershed

VL-4651-A ✖

VL-4651-A




IMG_0027358.jpg

COF MS4 ID	VL-4651-A
Watershed	Volanta
Material	RCP
Shape_1	Arch
Depth	0
Top Width	0
Bottom Width	0
Type	Closed Pipe
Category	
Outfall_No	<Null>
Comment	22x36 rcp
Flow Description	Trickle
Outfall Damage	
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	1
Diameter	36
Submerged in Water	No
Submerged With Sediment	No
Date Collected	7/6/2012
2012 Photo 1	0027358
2012 Photo 2	<Null>

City of Fairhope - Outfall Inventory Volanta Watershed

VL-4651-B



IMG_0027359.jpg

COF MS4 ID	VL-4651-B
Watershed	Volanta
Material	CMP
Shape_1	Circular
Depth	0
Top Width	0
Bottom Width	0
Type	Closed Pipe
Category	
Outfall_No	<Null>
Comment	
Flow Description	None
Outfall Damage	
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	1
Diameter	48
Submerged in Water	No
Submerged With Sediment	No
Date Collected	7/6/2012
2012 Photo 1	0027359
2012 Photo 2	<Null>

City of Fairhope - Outfall Inventory Volanta Watershed


VL-47625-A ✖

VL-47625-A



IMG_0027360.jpg


COF MS4 ID	VL-47625-A
Watershed	Volanta
Material	HDPE
Shape_1	Circular
Depth	0
Top Width	0
Bottom Width	0
Type	Closed Pipe
Category	
Outfall_No	<Null>
Comment	
Flow Description	None
Outfall Damage	
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	Orange
Barrels	1
Diameter	24
Submerged in Water	No
Submerged With Sediment	No
Date Collected	7/6/2012
2012 Photo 1	0027360
2012 Photo 2	<Null>



City of Fairhope - Outfall Inventory Volanta Watershed


VL-47625-B ✖

VL-47625-B



IMG_0027361.jpg

COF MS4 ID	VL-47625-B
Watershed	Volanta
Material	RCP
Shape_1	Circular
Depth	0
Top Width	0
Bottom Width	0
Type	Closed Pipe
Category	
Outfall_No	<Null>
Comment	Parking discharge
Flow Description	None
Outfall Damage	
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	1
Diameter	24
Submerged in Water	No
Submerged With Sediment	Partially
Date Collected	7/6/2012
2012 Photo 1	0027361
2012 Photo 2	<Null>



City of Fairhope - Outfall Inventory Volanta Watershed

VL-47625-C

VL-47625-C


IMG_0027362.jpg

COF MS4 ID	VL-47625-C
Watershed	Volanta
Material	RCP
Shape_1	Box
Depth	0
Top Width	0
Bottom Width	0
Type	Closed Pipe
Category	
Outfall_No	<Null>
Comment	5x5 box under Section
Flow Description	None
Outfall Damage	
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	2
Diameter	60
Submerged in Water	No
Submerged With Sediment	Partially
Date Collected	7/6/2012
2012 Photo 1	0027362
2012 Photo 2	<Null>

City of Fairhope - Outfall Inventory Volanta Watershed

VL-47625-D


VL-47625-D



IMG_0027363.jpg

[IMG_0027363.jpg](#) [IMG_0028364.jpg](#)


COF MS4 ID	VL-47625-D
Watershed	Volanta
Material	Rip_rap
Shape_1	Trapezoid
Depth	4
Top Width	20
Bottom Width	10
Type	Open Drainage
Category	
Outfall_No	<Null>
Comment	Armored ditch
Flow Description	None
Outfall Damage	
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	
Diameter	0
Submerged in Water	
Submerged With Sediment	
Date Collected	7/6/2012
2012 Photo 1	0027363
2012 Photo 2	0028364



City of Fairhope - Outfall Inventory Volanta Watershed

VL-56062-A

VL-56062-A




IMG_0025341.jpg

COF MS4 ID	VL-56062-A
Watershed	Volanta
Material	Rip_rap
Shape_1	Other
Depth	2
Top Width	20
Bottom Width	20
Type	Open Drainage
Category	
Outfall_No	<Null>
Comment	Stabilization work beginning
Flow Description	None
Outfall Damage	
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	
Diameter	0
Submerged in Water	
Submerged With Sediment	
Date Collected	7/6/2012
2012 Photo 1	0025341
2012 Photo 2	<Null>

City of Fairhope - Outfall Inventory Volanta Watershed

VL-56062-B



IMG_0026342.jpg

[IMG_0026342.jpg](#)
[IMG_0027343.jpg](#)

COF MS4 ID	VL-56062-B
Watershed	Volanta
Material	Rip_rap
Shape_1	Other
Depth	6
Top Width	20
Bottom Width	20
Type	Open Drainage
Category	
Outfall_No	<Null>
Comment	Stabilization ended
Flow Description	
Outfall Damage	
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	
Diameter	0
Submerged in Water	
Submerged With Sediment	
Date Collected	7/6/2012
2012 Photo 1	0026342
2012 Photo 2	0027343

City of Fairhope - Outfall Inventory Volanta Watershed

VL-5613-A


VL-5613-A

IMG_0051723.jpg

[IMG_0051723.jpg](#) [IMG_0052724.jpg](#)


COF MS4 ID	VL-5613-A
Watershed	Volanta
Material	Earthen
Shape_1	Other
Depth	0
Top Width	0
Bottom Width	0
Type	Open Drainage
Category	Private
Outfall_No	<Null>
Comment	Private retention pond
Flow Description	
Outfall Damage	
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	<Null>
Diameter	<Null>
Submerged in Water	<Null>
Submerged With Sediment	<Null>
Date Collected	10/1/2012
2012 Photo 1	0051723
2012 Photo 2	0052724

City of Fairhope - Outfall Inventory Volanta Watershed



VL-56704-A


VL-56704-A



IMG_0027351.jpg


COF MS4 ID	VL-56704-A
Watershed	Volanta
Material	RCP
Shape_1	Circular
Depth	0
Top Width	0
Bottom Width	0
Type	Closed Pipe
Category	
Outfall_No	<Null>
Comment	Under Myrtle
Flow Description	None
Outfall Damage	
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	1
Diameter	42
Submerged in Water	No
Submerged With Sediment	No
Date Collected	7/6/2012
2012 Photo 1	0027351
2012 Photo 2	<Null>

City of Fairhope - Outfall Inventory Volanta Watershed



VL-72822-A

VL-72822-A




IMG_0027353.jpg

COF MS4 ID	VL-72822-A
Watershed	Volanta
Material	CMP
Shape_1	Elliptical
Depth	0
Top Width	0
Bottom Width	0
Type	Closed Pipe
Category	
Outfall_No	<Null>
Comment	Under street
Flow Description	Trickle
Outfall Damage	
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	3
Diameter	56
Submerged in Water	Partially
Submerged With Sediment	Partially
Date Collected	7/6/2012
2012 Photo 1	0027353
2012 Photo 2	<Null>

City of Fairhope - Outfall Inventory Volanta Watershed

VL-73246-A

VL-73246-A




IMG_0027352.jpg

COF MS4 ID	VL-73246-A
Watershed	Volanta
Material	CMP
Shape_1	Circular
Depth	0
Top Width	0
Bottom Width	0
Type	Closed Pipe
Category	
Outfall_No	<Null>
Comment	
Flow Description	Trickle
Outfall Damage	
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	1
Diameter	48
Submerged in Water	Partially
Submerged With Sediment	No
Date Collected	7/6/2012
2012 Photo 1	0027352
2012 Photo 2	<Null>

City of Fairhope - Outfall Inventory Volanta Watershed

VL-73246-B

VL-73246-B




IMG_0027354.jpg

COF MS4 ID	VL-73246-B
Watershed	Volanta
Material	HDPE
Shape_1	Circular
Depth	0
Top Width	0
Bottom Width	0
Type	Closed Pipe
Category	
Outfall_No	<Null>
Comment	
Flow Description	None
Outfall Damage	
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	1
Diameter	24
Submerged in Water	Partially
Submerged With Sediment	No
Date Collected	7/6/2012
2012 Photo 1	0027354
2012 Photo 2	<Null>

City of Fairhope - Outfall Inventory Volanta Watershed

VL-89431-A



IMG_0027357.jpg

COF MS4 ID	VL-89431-A
Watershed	Volanta
Material	RCP
Shape_1	Circular
Depth	0
Top Width	0
Bottom Width	0
Type	Closed Pipe
Category	
Outfall_No	<Null>
Comment	Outlet box
Flow Description	None
Outfall Damage	
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	1
Diameter	24
Submerged in Water	No
Submerged With Sediment	Partially
Date Collected	7/6/2012
2012 Photo 1	0027357
2012 Photo 2	<Null>