

ADDENDUM NO. 01
CITY OF FAIRHOPE

Bid No.016-19 Wood Pole Inspections and Inventory Survey RE-BID

Item IV, SCOPE OF WORK AND SPECIFICATIONS FOR IN-SERVICE WOOD POLE INSPECTION (SOUND AND BORE) AND INVENTORY, General Section, 1.3 Contractor Requirements

CURRENT

CONTRACTOR is required to have a minimum of 5 years in the in-service pole inspection business. **CONTRACTOR** must have documented programs/policies conforming to the Occupational Safety and Health Administration (“OSHA”) and the Department of Transportation (“DOT”). These policies must include a safety manual and and OSHA regulations involving Personal Protective Equipment (“PPE”). **Safe Work Practices** are a condition of this contract and **CONTRACTORS** are expected to follow all safety guidelines. **CONTRACTOR** must have a current Interstate Experience Modification Rate (EMR) safety rating of less than 0.80 for 3 years or more (**notarized documentation from CONTRACTOR’s insurance carrier must be included in proposal**). Furthermore, **CONTRACTORS** 2018 TRIR (Total Recordable Incident Rate) must be 2.50 or less. The 2018 average Utility (electrical) is 3.0.

REVISED

CONTRACTOR is required to have a minimum of 5 years in the in-service pole inspection business. **CONTRACTOR** must have documented programs/policies conforming to the Occupational Safety and Health Administration (“OSHA”) and the Department of Transportation (“DOT”). These policies must include a safety manual and OSHA regulations involving Personal Protective Equipment (“PPE”). **Safe Work Practices** are a condition of this contract and **CONTRACTORS** are expected to follow all safety guidelines. **CONTRACTOR** must supply **OWNER** their last three years’ Experience Modification Rate (EMR). Furthermore, **CONTRACTORS** 2018 TRIR (Total Recordable Incident Rate) must be 2.50 or less. **CONTRACTOR** must provide EMR and TRIR verification upon award of contract.

Bidders are to sign and include signed **Addendum No. 1** with submitted bid documents.

Acknowledged:

Company

By