



City of Fairhope - Outfall Inventory Pensacola Worm Branch Watershed

PWB-14734-A



IMG_0051694.jpg

COF MS4 ID	PWB-14734-A
Watershed	Pensacola Worm Branch
Material	RCP
Shape_1	Circular
Depth	0
Top Width	0
Bottom Width	0
Type	Closed Pipe
Category	Private
Outfall_No	<Null>
Comment	Private retention discharge
Flow Description	Trickle
Outfall Damage	
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	1
Diameter	36
Submerged in Water	No
Submerged With Sediment	No
Date Collected	8/24/2012
2012 Photo 1	0051694
2012 Photo 2	<Null>



City of Fairhope - Outfall Inventory
Pensacola Worm Branch Watershed

The screenshot displays a GIS interface. On the right, an aerial photograph shows a residential property outlined in red. A blue dot on the property indicates the location of the outfall. On the left, a data popup window for 'PWB-14734-B' is open, containing a photo of a grassy field and a table of metadata.

PWB-14734-B	
COF MS4 ID	PWB-14734-B
Watershed	Pensacola Worm Branch
Material	Earthen
Shape_1	Other
Depth	0
Top Width	0
Bottom Width	0
Type	Open Drainage
Category	Private
Outfall_No	<Null>
Comment	Private retention pond
Flow Description	
Outfall Damage	
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	0
Diameter	0
Submerged in Water	0
Submerged With Sediment	0
Date Collected	8/24/2012
2012 Photo 1	0051693
2012 Photo 2	<Null>

City of Fairhope - Outfall Inventory
Pensacola Worm Branch Watershed

PWB-261672-A

IMG_0051702.jpg

COF MS4 ID	PWB-261672-A
Watershed	Pensacola Worm Branch
Material	Earthen
Shape_1	Other
Depth	0
Top Width	0
Bottom Width	0
Type	Open Drainage
Category	Private
Outfall_No	<Null>
Comment	Private retention pond
Flow Description	
Outfall Damage	
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	0
Diameter	0
Submerged in Water	0
Submerged With Sediment	0
Date Collected	8/24/2012
2012 Photo 1	0051702
2012 Photo 2	<Null>

City of Fairhope - Outfall Inventory
Pensacola Worm Branch Watershed

PWB-261846-A

PWB-261846-A

IMG_0015173.jpg

COF MS4 ID	PWB-261846-A
Watershed	Pensacola Worm Branch
Material	HDPE
Shape_1	Circular
Depth	0
Top Width	0
Bottom Width	0
Type	Closed Pipe
Category	Private
Outfall_No	<Null>
Comment	Private retention discharge
Flow Description	None
Outfall Damage	
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	1
Diameter	18
Submerged in Water	Partially
Submerged With Sediment	No
Date Collected	6/22/2012
2012 Photo 1	0015173
2012 Photo 2	<Null>

City of Fairhope – Outfall Inventory
 Pensacola Worm Branch Watershed

PWB-269693-A

PWB-269693-A

IMG_0051697.jpg

COF MS4 ID	PWB-269693-A
Watershed	Pensacola Worm Branch
Material	Earthen
Shape_1	Other
Depth	0
Top Width	0
Bottom Width	0
Type	Open Drainage
Category	Private
Outfall_No	<Null>
Comment	Private retention pond
Flow Description	
Outfall Damage	
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	0
Diameter	0
Submerged in Water	0
Submerged With Sediment	0
Date Collected	8/24/2012
2012 Photo 1	0051697
2012 Photo 2	<Null>

City of Fairhope - Outfall Inventory
Pensacola Worm Branch Watershed

PWB-269693-B

PWB-269693-B

IMG_0051698.jpg

COF MS4 ID	PWB-269693-B
Watershed	Pensacola Worm Branch
Material	Concrete
Shape_1	Other
Depth	1
Top Width	9
Bottom Width	9
Type	Open Drainage
Category	Private
Outfall_No	<Null>
Comment	Private retention discharge structure
Flow Description	Trickle
Outfall Damage	
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	Green
Barrels	0
Diameter	0
Submerged in Water	0
Submerged With Sediment	0
Date Collected	8/24/2012
2012 Photo 1	0051698
2012 Photo 2	<Null>

City of Fairhope - Outfall Inventory
 Pensacola Worm Branch Watershed

PWB-269693-C

PWB-269693-C

IMG_0051699.jpg


IMG_0051699.jpg | IMG_0052700.jpg

COF MS4 ID	PWB-269693-C
Watershed	Pensacola Worm Branch
Material	Earthen
Shape_1	Other
Depth	3
Top Width	3
Bottom Width	2
Type	Open Drainage
Category	
Outfall_No	<Null>
Comment	Ditch downstream from discharge
Flow Description	Trickle
Outfall Damage	
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	0
Diameter	0
Submerged in Water	0
Submerged With Sediment	0
Date Collected	8/24/2012
2012 Photo 1	0051699
2012 Photo 2	0052700

City of Fairhope – Outfall Inventory
 Pensacola Worm Branch Watershed

PWB-270376-A


PWB-270376-A



IMG_0015171.jpg

[IMG_0015171.jpg](#) [IMG_0016172.jpg](#)

COF MS4 ID	PWB-270376-A
Watershed	Pensacola Worm Branch
Material	
Shape_1	Trapezoid
Depth	3
Top Width	16
Bottom Width	5
Type	Open Drainage
Category	Private
Outfall_No	<Null>
Comment	Private retention discharge
Flow Description	Trickle
Outfall Damage	
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	Oil_Sheen
Pipe Benthic Growth	Orange
Barrels	
Diameter	0
Submerged in Water	
Submerged With Sediment	
Date Collected	6/22/2012
2012 Photo 1	0015171
2012 Photo 2	0016172



City of Fairhope – Outfall Inventory
 Pensacola Worm Branch Watershed


PWB-280514-A

PWB-280514-A

IMG_0051701.jpg

COF MS4 ID	PWB-280514-A
Watershed	Pensacola Worm Branch
Material	Earthen
Shape_1	Other
Depth	0
Top Width	0
Bottom Width	0
Type	Open Drainage
Category	Private
Outfall_No	<Null>
Comment	Private retention pond
Flow Description	
Outfall Damage	
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	0
Diameter	0
Submerged in Water	0
Submerged With Sediment	0
Date Collected	8/24/2012
2012 Photo 1	0051701
2012 Photo 2	<Null>

City of Fairhope - Outfall Inventory
Pensacola Worm Branch Watershed



PWB-281003-A

PWB-281003-A


IMG_0015175.jpg

COF MS4 ID	PWB-281003-A
Watershed	Pensacola Worm Branch
Material	Concrete
Shape_1	Other
Depth	0
Top Width	0
Bottom Width	0
Type	Open Drainage
Category	Private
Outfall_No	<Null>
Comment	Private retention discharge concrete checkdam
Flow Description	Trickle
Outfall Damage	
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	Other
Pipe Benthic Growth	
Barrels	
Diameter	0
Submerged in Water	
Submerged With Sediment	
Date Collected	6/22/2012
2012 Photo 1	0015175
2012 Photo 2	<Null>

City of Fairhope - Outfall Inventory
Pensacola Worm Branch Watershed

PWB-281003-B


PWB-281003-B



IMG_0015176.jpg

[IMG_0015176.jpg](#) | [IMG_0016177.jpg](#)

COF MS4 ID	PWB-281003-B
Watershed	Pensacola Worm Branch
Material	Earthen
Shape_1	Other
Depth	0
Top Width	0
Bottom Width	0
Type	Open Drainage
Category	Private
Outfall_No	<Null>
Comment	Private retention
Flow Description	
Outfall Damage	
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	
Diameter	0
Submerged in Water	
Submerged With Sediment	
Date Collected	6/22/2012
2012 Photo 1	0015176
2012 Photo 2	0016177



City of Fairhope - Outfall Inventory
 Pensacola Worm Branch Watershed

PWB-293901-A

PWB-293901-A

IMG_0051695.jpg

COF MS4 ID	PWB-293901-A
Watershed	Pensacola Worm Branch
Material	Earthen
Shape_1	Other
Depth	0
Top Width	0
Bottom Width	0
Type	Open Drainage
Category	Private
Outfall_No	<Null>
Comment	Private retention pond
Flow Description	
Outfall Damage	
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	0
Diameter	0
Submerged in Water	0
Submerged With Sediment	0
Date Collected	8/24/2012
2012 Photo 1	0051695
2012 Photo 2	<Null>

City of Fairhope - Outfall Inventory
 Pensacola Worm Branch Watershed

PWB-293927-A

PWB-293927-A


IMG_0051696.jpg

COF MS4 ID	PWB-293927-A
Watershed	Pensacola Worm Branch
Material	RCP
Shape_1	Circular
Depth	0
Top Width	0
Bottom Width	0
Type	Closed Pipe
Category	Private
Outfall_No	<Null>
Comment	Private retention pond discharge
Flow Description	None
Outfall Damage	
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	1
Diameter	36
Submerged in Water	No
Submerged With Sediment	No
Date Collected	8/24/2012
2012 Photo 1	0051696
2012 Photo 2	<Null>

City of Fairhope Storm Sewer Inventory

Pensacola Worm Branch Watershed

Data File Name: PWB-369810



The Tracery wet pond

Address of storm water facility: Ornate Avenue next to Lot 34 (north side of Lawrence Rd)

Property PIN# 369810

Material: Earthen (1) Detention Pond ("Pond Detention") w/stilling basin

Type: Open Drainage (OD)

Category: Private (subdivision)

Comment: One of one pond in subdivision

Outfall: Wetlands

*This information was added to GIS/Storm Sewer Inventory on: 4/13/2020 *Hard copy only**

14