

Report User: TMan0001

SSO ID: 19257

Print Date: 4/18/2021

\* require for submission

 require for completion

## Report Form

Facility Name:	<b>Fairhope WWTP</b>
Permit Number:	<b>AL0020842</b>
* Date/Time SSO Began:	<b>4/17/2021 3:10:00 PM</b>
* Is SSO currently ongoing?	<input type="radio"/> Yes <input checked="" type="radio"/> No
<input checked="" type="checkbox"/> Date/Time SSO Stopped:	<b>4/18/2021 3:00:00 AM</b>
<input checked="" type="checkbox"/> Did the SSO occur during wet weather?	<input checked="" type="radio"/> Yes <input type="radio"/> No
<input checked="" type="checkbox"/> Was the SSO caused by an extreme weather event (e.g. hurricane)?	<input type="radio"/> Yes <input checked="" type="radio"/> No
<input checked="" type="checkbox"/> Report Estimated Volume as	<input checked="" type="radio"/> Value <input type="radio"/> Range
<input checked="" type="checkbox"/> Estimated Volume	<b>30000</b> gallons
<input checked="" type="checkbox"/> Was the Department notified within 24 hours? (If report online, verbal notification is not required)	<input checked="" type="radio"/> Yes <input type="radio"/> No
<input checked="" type="checkbox"/> Date/Time of Notification:	<b>4/18/2021 7:20:00 AM</b>
<input checked="" type="checkbox"/> Method of notification:	<input type="radio"/> Verbal/Telephone <input checked="" type="radio"/> Electronic via eSSO <input type="radio"/> Other
<input checked="" type="checkbox"/> Source of Discharge Event: (check all that apply)	<input checked="" type="checkbox"/> manhole <input type="checkbox"/> lift station <input type="checkbox"/> broken line <input type="checkbox"/> cleanout <input type="checkbox"/> treatment plant <input type="checkbox"/> other <input type="text"/>
* Location of Discharge(address,etc) (not required if " Lat/Long of Discharge " is reported)	<b>419 Valley Street, area of Valley Street Lift Station, Manhole Middle St and Valley St</b>
* Lat/Long of Discharge (not required if " Location of Discharge " is reported)	Latitude: <b>30.513834</b> Longitude: <b>-87.898349</b>
<input checked="" type="checkbox"/> Known or Suspected Cause of Discharge	<b>Infiltration into the collection system by severe weather the last week causing ground saturation with near 3 inches of rain in the last 12 hours.</b>
<input checked="" type="checkbox"/> Ultimate Destination of Discharge (check all that apply)	<input type="checkbox"/> ground absorbed <input checked="" type="checkbox"/> creek or river (Provide name) <b>BIG HEAD GULLY (26257)</b> <input type="checkbox"/> Un-named Tributary <input type="checkbox"/> storm drain <input checked="" type="checkbox"/> drainage ditch <input type="checkbox"/> backup into building/residence <input type="checkbox"/> other (describe) <input type="text"/>
<input checked="" type="checkbox"/> Did the Discharge reach swimming water?	<input type="radio"/> Yes <input checked="" type="radio"/> No <input type="radio"/> Unknown
<input checked="" type="checkbox"/> Monitoring of the Receiving Water (i.e. visual survey or water quality sampling) Is	<input type="radio"/> complete <input type="radio"/> ongoing <input checked="" type="radio"/> not necessary

Was the affected area

Cleaned?  Yes  No    Disinfected?  Yes  No

Are you aware of any other potential health or environmental impacts

No  Yes    If Yes, please describe:

Describe corrective actions taken, plans to eliminate future discharges, and actions or plans to mitigate impacts to the environment and/or public health

**Continue to investigate by video and smoke testing to find infiltration into the sewer system. Repair anything found.**

Indicate Efforts to Notify Public

(check all that apply)

press release

\* Date Public Was Notified: **4/18/2021**

placement of signs

\* Date Public Was Notified: **4/17/2021**

other

notice not required because:

County Health Department

\* Date Other Officials Were Notified: **4/18/2021**

State Health Department

other

notice not required because:

Indicate Other Officials Notified

(check all that apply)

Other States:

Were any public water supply intake locations affected?

Yes  No

Facility SSO Report ID

N/A

**General Comment**

General Report Comment and Explanation

**Severe weather the last week causing ground saturation with an additional 3 inches of rain in the last 12 hours caused a manhole in the area of the Valley Street lift station (419 Valley St Fairhope) to spill approximately 30,000 gallons into the ditch that leads to Big Head Gully.**