


City of Fairhope - Outfall Inventory Bay Outfall Watershed


FC-205197-B ✖

FC-205197-B



IMG_0013135.jpg


COF MS4 ID	FC-205197-B
Watershed	Fly Creek
Material	Other
Shape_1	Other
Depth	0
Top Width	0
Bottom Width	0
Type	Open Drainage
Category	Bay Outfall
Outfall_No	1
Comment	Outfall to bay, Fly Creek
Flow Description	
Outfall Damage	
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	
Diameter	0
Submerged in Water	
Submerged With Sediment	
Date Collected	6/21/2012
2012 Photo 1	0013135
2012 Photo 2	<Null>



City of Fairhope - Outfall Inventory Bay Outfall Watershed


RC-77980-A

RC-77980-A



IMG_0013127.jpg


COF MS4 ID	RC-77980-A
Watershed	Rock Creek
Material	Other
Shape_1	Other
Depth	0
Top Width	0
Bottom Width	0
Type	Open Drainage
Category	Bay Outfall
Outfall_No	2
Comment	Rock Creek outfall
Flow Description	
Outfall Damage	
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	
Diameter	0
Submerged in Water	
Submerged With Sediment	
Date Collected	6/21/2012
2012 Photo 1	0013127
2012 Photo 2	<Null>



City of Fairhope - Outfall Inventory Bay Outfall Watershed


SG-12795-A ✖

SG-12795-A



IMG_0019306.jpg

COF MS4 ID	SG-12795-A
Watershed	Stack Gully
Material	HDPE
Shape_1	Circular
Depth	0
Top Width	0
Bottom Width	0
Type	Closed Pipe
Category	Bay Outfall
Outfall_No	3
Comment	Bay outfall
Flow Description	None
Outfall Damage	
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	1
Diameter	24
Submerged in Water	No
Submerged With Sediment	No
Date Collected	7/3/2012
2012 Photo 1	0019306
2012 Photo 2	<Null>



City of Fairhope – Outfall Inventory Bay Outfall Watershed

SG-12795-B

SG-12795-B


IMG_0019307.jpg

COF MS4 ID	SG-12795-B
Watershed	Stack Gully
Material	HDPE
Shape_1	Circular
Depth	0
Top Width	0
Bottom Width	0
Type	Closed Pipe
Category	Bay Outfall
Outfall_No	4
Comment	Bay outfall
Flow Description	Trickle
Outfall Damage	
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	1
Diameter	24
Submerged in Water	Partially
Submerged With Sediment	No
Date Collected	7/3/2012
2012 Photo 1	0019307
2012 Photo 2	<Null>

City of Fairhope - Outfall Inventory Bay Outfall Watershed

SG-12795-C ✖

SG-12795-C



IMG_0019308.jpg

COF MS4 ID	SG-12795-C
Watershed	Stack Gully
Material	HDPE
Shape_1	Circular
Depth	0
Top Width	0
Bottom Width	0
Type	Closed Pipe
Category	Bay Outfall
Outfall_No	5
Comment	Bay outfall
Flow Description	None
Outfall Damage	
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	1
Diameter	24
Submerged in Water	No
Submerged With Sediment	No
Date Collected	7/3/2012
2012 Photo 1	0019308
2012 Photo 2	<Null>



City of Fairhope - Outfall Inventory Bay Outfall Watershed

TG-61465-A ✖

TG-61465-A



IMG_0019313.jpg

[IMG_0019313.jpg](#) [IMG_0020314.jpg](#)

COF MS4 ID	TG-61465-A
Watershed	Tatumville Gully
Material	CMP
Shape_1	Circular
Depth	0
Top Width	0
Bottom Width	0
Type	Closed Pipe
Category	Bay Outfall
Outfall_No	6
Comment	Bay outfall
Flow Description	None
Outfall Damage	Corrosion
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	1
Diameter	24
Submerged in Water	No
Submerged With Sediment	No
Date Collected	7/3/2012
2012 Photo 1	0019313
2012 Photo 2	0020314




City of Fairhope - Outfall Inventory Bay Outfall Watershed

COF MS4 ID	TG-61465-B
Watershed	Tatumville Gully
Material	CMP
Shape_1	Circular
Depth	0
Top Width	0
Bottom Width	0
Type	Closed Pipe
Category	Bay Outfall
Outfall_No	7
Comment	Bay outfall
Flow Description	None
Outfall Damage	Crushed
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	1
Diameter	24
Submerged in Water	Partially
Submerged With Sediment	No
Date Collected	7/3/2012
2012 Photo 1	0019315
2012 Photo 2	<Null>

City of Fairhope - Outfall Inventory Bay Outfall Watershed

SG-64364-A

SG-64364-A



IMG_0019309.jpg

COF MS4 ID	SG-64364-A
Watershed	Stack Gully
Material	Concrete
Shape_1	Trapezoid
Depth	2
Top Width	6
Bottom Width	2
Type	Open Drainage
Category	Bay Outfall
Outfall_No	8
Comment	Bay outfall
Flow Description	None
Outfall Damage	
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	
Diameter	0
Submerged in Water	
Submerged With Sediment	
Date Collected	7/3/2012
2012 Photo 1	0019309
2012 Photo 2	<Null>

City of Fairhope - Outfall Inventory Bay Outfall Watershed

TG-61465-C
✖

TG-61465-C





COF MS4 ID	TG-61465-C
Watershed	Tatumville Gully
Material	Concrete
Shape_1	Trapezoid
Depth	4
Top Width	0
Bottom Width	20
Type	Open Drainage
Category	Major Bay Outfall
Outfall_No	9
Comment	Major bay outfall
Flow Description	Trickle
Outfall Damage	
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	
Diameter	0
Submerged in Water	
Submerged With Sediment	
Date Collected	7/3/2012
2012 Photo 1	0019312
2012 Photo 2	<Null>



City of Fairhope - Outfall Inventory Bay Outfall Watershed

VL-43887-A
✖

VL-43887-A

IMG_0015203.jpg


[IMG_0015203.jpg](#) [IMG_0016204.jpg](#)

COF MS4 ID	VL-43887-A
Watershed	Volanta
Material	Earthen
Shape_1	Trapezoid
Depth	4
Top Width	20
Bottom Width	12
Type	Open Drainage
Category	Bay Outfall
Outfall_No	10
Comment	Volanta Gulley discharge to Bay
Flow Description	Trickle
Outfall Damage	
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	
Diameter	0
Submerged in Water	
Submerged With Sediment	
Date Collected	7/2/2012
2012 Photo 1	0015203
2012 Photo 2	0016204

City of Fairhope – Outfall Inventory Bay Outfall Watershed


SG-12788-A x3

SG-12788-A



IMG_00004.jpg

COF MS4 ID	SG-12788-A
Watershed	Stack Gully
Material	RCP
Shape_1	Circular
Depth	0
Top Width	0
Bottom Width	0
Type	Closed Pipe
Category	Major Bay Outfall
Outfall_No	11
Comment	
Flow Description	Trickle
Outfall Damage	Spalling_Cracking_Ch
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	Green
Barrels	1
Diameter	36
Submerged in Water	No
Submerged With Sediment	No
Date Collected	6/14/2012
2012 Photo 1	00004
2012 Photo 2	<Null>



City of Fairhope - Outfall Inventory Bay Outfall Watershed

SG-64362-E

SG-64362-E

IMG_00001.jpg

COF MS4 ID	SG-64362-E
Watershed	Stack Gully
Material	HDPE
Shape_1	Circular
Depth	0
Top Width	0
Bottom Width	0
Type	Closed Pipe
Category	Major Bay Outfall
Outfall_No	12
Comment	
Flow Description	Trickle
Outfall Damage	Spalling_Cracking_Ch
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	2
Diameter	42
Submerged in Water	No
Submerged With Sediment	No
Date Collected	6/14/2012
2012 Photo 1	00001
2012 Photo 2	<Null>

City of Fairhope - Outfall Inventory Bay Outfall Watershed

BMG-40542-C ✖


BMG-40542-C



IMG_0015219.jpg

[IMG_0015219.jpg](#) | [IMG_0016220.jpg](#)


COF MS4 ID	BMG-40542-C
Watershed	Big Mouth Gully
Material	Earthen
Shape_1	Other
Depth	3
Top Width	0
Bottom Width	0
Type	Open Drainage
Category	Major Bay Outfall
Outfall_No	13
Comment	Gulley discharge to bay
Flow Description	Substantial
Outfall Damage	
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	
Diameter	0
Submerged in Water	
Submerged With Sediment	
Date Collected	7/2/2012
2012 Photo 1	0015219
2012 Photo 2	0016220



City of Fairhope - Outfall Inventory Bay Outfall Watershed


RC-59793-A ✖

RC-59793-A



IMG_0013126.jpg

COF MS4 ID	RC-59793-A
Watershed	Rock Creek
Material	CMP
Shape_1	Circular
Depth	0
Top Width	0
Bottom Width	0
Type	Closed Pipe
Category	Bay Outfall
Outfall_No	
Comment	Bay outfall
Flow Description	Trickle
Outfall Damage	
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	1
Diameter	24
Submerged in Water	Partially
Submerged With Sediment	Partially
Date Collected	6/21/2012
2012 Photo 1	0013126
2012 Photo 2	<Null>



City of Fairhope - Outfall Inventory Bay Outfall Watershed

FC-205197-A


FC-205197-A




IMG_0013133.jpg

[IMG_0013133.jpg](#)
[IMG_0014134.jpg](#)

COF MS4 ID	FC-205197-A
Watershed	Fly Creek
Material	Other
Shape_1	Other
Depth	0
Top Width	5
Bottom Width	5
Type	Open Drainage
Category	
Outfall_No	<Null>
Comment	Overland flow from parking
Flow Description	None
Outfall Damage	
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	
Diameter	0
Submerged in Water	
Submerged With Sediment	
Date Collected	6/21/2012
2012 Photo 1	0013133
2012 Photo 2	0014134



City of Fairhope - Outfall Inventory Bay Outfall Watershed



VL-102308-E

VL-102308-E

IMG_0015200.jpg

COF MS4 ID	VL-102308-E
Watershed	Volanta
Material	Concrete
Shape_1	Other
Depth	1
Top Width	20
Bottom Width	20
Type	Open Drainage
Category	
Outfall_No	<Null>
Comment	Boat launch discharge
Flow Description	None
Outfall Damage	
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	
Diameter	0
Submerged in Water	
Submerged With Sediment	
Date Collected	7/2/2012
2012 Photo 1	0015200
2012 Photo 2	<Null>

City of Fairhope – Outfall Inventory Bay Outfall Watershed

VL-102308-D

VL-102308-D




IMG_0015199.jpg

COF MS4 ID	VL-102308-D
Watershed	Volanta
Material	Earthen
Shape_1	Other
Depth	2
Top Width	6
Bottom Width	2
Type	Open Drainage
Category	
Outfall_No	<Null>
Comment	Parking discharge
Flow Description	None
Outfall Damage	
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	
Diameter	0
Submerged in Water	
Submerged With Sediment	
Date Collected	7/2/2012
2012 Photo 1	0015199
2012 Photo 2	<Null>



City of Fairhope - Outfall Inventory Bay Outfall Watershed

VL-102308-C




VL-102308-C

IMG_0015197.jpg

[IMG_0015197.jpg](#) | [IMG_0016198.jpg](#)

COF MS4 ID	VL-102308-C
Watershed	Volanta
Material	Earthen
Shape_1	Other
Depth	2
Top Width	20
Bottom Width	2
Type	Open Drainage
Category	
Outfall_No	<Null>
Comment	Volanta Street discharge
Flow Description	None
Outfall Damage	
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	
Diameter	0
Submerged in Water	
Submerged With Sediment	
Date Collected	7/2/2012
2012 Photo 1	0015196
2012 Photo 2	0016198



City of Fairhope - Outfall Inventory Bay Outfall Watershed

BMG-27699-B


IMG_0015213.jpg

COF MS4 ID	BMG-27699-B
Watershed	Big Mouth Gully
Material	Earthen
Shape_1	Other
Depth	2
Top Width	8
Bottom Width	2
Type	Open Drainage
Category	
Outfall_No	<Null>
Comment	At Bay Shore
Flow Description	None
Outfall Damage	
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	
Diameter	0
Submerged in Water	
Submerged With Sediment	
Date Collected	7/2/2012
2012 Photo 1	0015213
2012 Photo 2	<Null>

City of Fairhope – Outfall Inventory Bay Outfall Watershed

BMG-69776-A ✖

BMG-69776-A




IMG_0015214.jpg

COF MS4 ID	BMG-69776-A
Watershed	Big Mouth Gully
Material	Earthen
Shape_1	Other
Depth	2
Top Width	5
Bottom Width	2
Type	Open Drainage
Category	
Outfall_No	<Null>
Comment	
Flow Description	None
Outfall Damage	
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	
Diameter	0
Submerged in Water	
Submerged With Sediment	
Date Collected	7/2/2012
2012 Photo 1	0015214
2012 Photo 2	<Null>




City of Fairhope – Outfall Inventory Bay Outfall Watershed



BMG-6515-A

BMG-6515-A




IMG_0015217.jpg

COF MS4 ID	BMG-6515-A
Watershed	Big Mouth Gully
Material	Earthen
Shape_1	Other
Depth	2
Top Width	5
Bottom Width	2
Type	Open Drainage
Category	
Outfall_No	<Null>
Comment	Below grand and mobile street discharge
Flow Description	None
Outfall Damage	
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	
Diameter	0
Submerged in Water	
Submerged With Sediment	
Date Collected	7/2/2012
2012 Photo 1	0015217
2012 Photo 2	<Null>

City of Fairhope – Outfall Inventory Bay Outfall Watershed


BMG-10058-A ✖

BMG-10058-A




IMG_0015218.jpg

COF MS4 ID	BMG-10058-A
Watershed	Big Mouth Gully
Material	Earthen
Shape_1	Other
Depth	0
Top Width	0
Bottom Width	0
Type	Open Drainage
Category	
Outfall_No	<Null>
Comment	Gulley discharge
Flow Description	Moderate
Outfall Damage	
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	
Diameter	0
Submerged in Water	
Submerged With Sediment	
Date Collected	7/2/2012
2012 Photo 1	0015218
2012 Photo 2	<Null>




City of Fairhope - Outfall Inventory Bay Outfall Watershed



BMG-64360-C

BMG-64360-C



IMG_0016250.jpg

COF MS4 ID	BMG-64360-C
Watershed	Big Mouth Gully
Material	Earthen
Shape_1	Trapezoid
Depth	3
Top Width	6
Bottom Width	3
Type	Open Drainage
Category	
Outfall_No	<Null>
Comment	
Flow Description	Trickle
Outfall Damage	
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	
Diameter	0
Submerged in Water	
Submerged With Sediment	
Date Collected	7/2/2012
2012 Photo 1	0016250
2012 Photo 2	<Null>

City of Fairhope - Outfall Inventory Bay Outfall Watershed



BMG-64360-B

BMG-64360-B


IMG_0016251.jpg

COF MS4 ID	BMG-64360-B
Watershed	Big Mouth Gully
Material	HDPE
Shape_1	Circular
Depth	0
Top Width	0
Bottom Width	0
Type	Closed Pipe
Category	
Outfall_No	<Null>
Comment	Duck pond discharge
Flow Description	Trickle
Outfall Damage	
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	1
Diameter	30
Submerged in Water	Partially
Submerged With Sediment	Partially
Date Collected	7/2/2012
2012 Photo 1	0016251
2012 Photo 2	<Null>

City of Fairhope - Outfall Inventory Bay Outfall Watershed

SG-64362-C

SG-64362-C



IMG_00003.jpg

COF MS4 ID	SG-64362-C
Watershed	Stack Gully
Material	RCP
Shape_1	Arch
Depth	0
Top Width	0
Bottom Width	0
Type	Closed Pipe
Category	
Outfall_No	<Null>
Comment	
Flow Description	None
Outfall Damage	
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	1
Diameter	0
Submerged in Water	No
Submerged With Sediment	No
Date Collected	6/14/2012
2012 Photo 1	00003
2012 Photo 2	<Null>

City of Fairhope - Outfall Inventory Bay Outfall Watershed

SG-64362-D

SG-64362-D


IMG_00002.jpg

COF MS4 ID	SG-64362-D
Watershed	Stack Gully
Material	RCP
Shape_1	Circular
Depth	0
Top Width	0
Bottom Width	0
Type	Closed Pipe
Category	
Outfall_No	
Comment	
Flow Description	Moderate
Outfall Damage	
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	1
Diameter	15
Submerged in Water	No
Submerged With Sediment	No
Date Collected	6/14/2012
2012 Photo 1	00002
2012 Photo 2	<Null>

City of Fairhope – Outfall Inventory Bay Outfall Watershed

TG-64364-A

TG-64364-A



IMG_0019310.jpg

COF MS4 ID	TG-64364-A
Watershed	Tatumville Gully
Material	Earthen
Shape_1	Trapezoid
Depth	2
Top Width	8
Bottom Width	4
Type	Open Drainage
Category	
Outfall_No	<Null>
Comment	Open ditch bay outfall
Flow Description	None
Outfall Damage	
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	
Diameter	0
Submerged in Water	
Submerged With Sediment	
Date Collected	7/3/2012
2012 Photo 1	0019310
2012 Photo 2	<Null>

