

City of Fairhope - Outfall Inventory Point Clear Creek Watershed

PCC-106166-A


PCC-106166-A

IMG_0035486.jpg

COF MS4 ID	PCC-106166-A
Watershed	Point Clear Creek
Material	RCP
Shape_1	Arch
Depth	0
Top Width	0
Bottom Width	0
Type	Closed Pipe
Category	
Outfall_No	<Null>
Comment	School retention pond discharge
Flow Description	
Outfall Damage	
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	1
Diameter	24
Submerged in Water	Partially
Submerged With Sediment	No
Date Collected	7/27/2012
2012 Photo 1	0035486
2012 Photo 2	<Null>


City of Fairhope - Outfall Inventory Point Clear Creek Watershed

PCC-106166-B



IMG_0035488.jpg

COF MS4 ID	PCC-106166-B
Watershed	Point Clear Creek
Material	RCP
Shape_1	Arch
Depth	0
Top Width	0
Bottom Width	0
Type	Closed Pipe
Category	
Outfall_No	<Null>
Comment	30x19
Flow Description	None
Outfall Damage	
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	1
Diameter	30
Submerged in Water	No
Submerged With Sediment	No
Date Collected	7/27/2012
2012 Photo 1	0035488
2012 Photo 2	<Null>



PIRATE DR


MANLEY RD

KEMPER LN

City of Fairhope - Outfall Inventory Point Clear Creek Watershed

PCC-106166-C

PCC-106166-C



IMG_0035481.jpg


[IMG_0035481.jpg](#) [IMG_0036482.jpg](#)

COF MS4 ID	PCC-106166-C
Watershed	Point Clear Creek
Material	Earthen
Shape_1	Other
Depth	0
Top Width	0
Bottom Width	0
Type	Open Drainage
Category	Private
Outfall_No	<Null>
Comment	Private retention pond
Flow Description	None
Outfall Damage	Corrosion
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	Excessive_Alg
Pipe Benthic Growth	
Barrels	
Diameter	0
Submerged in Water	
Submerged With Sediment	
Date Collected	7/27/2012
2012 Photo 1	0035481
2012 Photo 2	0036482

City of Fairhope - Outfall Inventory Point Clear Creek Watershed


PCC-106166-D
✖

PCC-106166-D



IMG_0035483.jpg


COF MS4 ID	PCC-106166-D
Watershed	Point Clear Creek
Material	Earthen
Shape_1	Other
Depth	0
Top Width	0
Bottom Width	0
Type	Open Drainage
Category	
Outfall_No	<Null>
Comment	School retention pond
Flow Description	
Outfall Damage	
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	
Diameter	0
Submerged in Water	
Submerged With Sediment	
Date Collected	7/27/2012
2012 Photo 1	0035483
2012 Photo 2	<Null>



City of Fairhope - Outfall Inventory Point Clear Creek Watershed


PCC-106166-E

PCC-106166-E



IMG_0035484.jpg


COF MS4 ID	PCC-106166-E
Watershed	Point Clear Creek
Material	Earthen
Shape_1	Other
Depth	0
Top Width	0
Bottom Width	0
Type	Open Drainage
Category	
Outfall_No	<Null>
Comment	School retention pond
Flow Description	
Outfall Damage	
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	
Diameter	0
Submerged in Water	
Submerged With Sediment	
Date Collected	7/27/2012
2012 Photo 1	0035484
2012 Photo 2	<Null>



City of Fairhope - Outfall Inventory Point Clear Creek Watershed


PCC-106166-F

PCC-106166-F



IMG_0035485.jpg

COF MS4 ID	PCC-106166-F
Watershed	Point Clear Creek
Material	Earthen
Shape_1	Trapezoid
Depth	2
Top Width	12
Bottom Width	2
Type	Open Drainage
Category	
Outfall_No	<Null>
Comment	Road discharge swale
Flow Description	None
Outfall Damage	
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	
Diameter	0
Submerged in Water	
Submerged With Sediment	
Date Collected	7/27/2012
2012 Photo 1	0035485
2012 Photo 2	<Null>



City of Fairhope - Outfall Inventory Point Clear Creek Watershed

PCC-106166-G


IMG_0035487.jpg

COF MS4 ID	PCC-106166-G
Watershed	Point Clear Creek
Material	Concrete
Shape_1	Trapezoid
Depth	1
Top Width	6
Bottom Width	6
Type	Open Drainage
Category	
Outfall_No	<Null>
Comment	Parking discharge
Flow Description	None
Outfall Damage	
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	
Diameter	0
Submerged in Water	
Submerged With Sediment	
Date Collected	7/27/2012
2012 Photo 1	0035487
2012 Photo 2	<Null>

City of Fairhope - Outfall Inventory Point Clear Creek Watershed

PCC-202853-A ✖


PCC-202853-A



IMG_0042562.jpg

[IMG_0042562.jpg](#) [IMG_0043561.jpg](#)


COF MS4 ID	PCC-202853-A
Watershed	Point Clear Creek
Material	Earthen
Shape_1	Other
Depth	0
Top Width	0
Bottom Width	0
Type	Open Drainage
Category	Private
Outfall_No	<Null>
Comment	Private retention pond
Flow Description	None
Outfall Damage	
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	0
Diameter	0
Submerged in Water	0
Submerged With Sediment	0
Date Collected	8/22/2012
2012 Photo 1	0043561
2012 Photo 2	0042562



City of Fairhope - Outfall Inventory Point Clear Creek Watershed

PCC-202853-B ✖


PCC-202853-B



IMG_0042563.jpg

[IMG_0042563.jpg](#) [IMG_0043564.jpg](#)


COF MS4 ID	PCC-202853-B
Watershed	Point Clear Creek
Material	RCP
Shape_1	Circular
Depth	0
Top Width	0
Bottom Width	0
Type	Closed Pipe
Category	Private
Outfall_No	<Null>
Comment	13x21 arch private retention discharge
Flow Description	None
Outfall Damage	
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	1
Diameter	21
Submerged in Water	No
Submerged With Sediment	Partially
Date Collected	8/22/2012
2012 Photo 1	0042563
2012 Photo 2	0043564



City of Fairhope - Outfall Inventory Point Clear Creek Watershed


PCC-243166-A ✖

PCC-243166-A



IMG_0035491.jpg


COF MS4 ID	PCC-243166-A
Watershed	Point Clear Creek
Material	Earthen
Shape_1	Other
Depth	0
Top Width	0
Bottom Width	0
Type	Open Drainage
Category	Private
Outfall_No	<Null>
Comment	Private retention pond
Flow Description	
Outfall Damage	
Deposits/Stains	
Abnormal Vegetation	Excessive
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	
Diameter	0
Submerged in Water	
Submerged With Sediment	
Date Collected	7/27/2012
2012 Photo 1	0035491
2012 Photo 2	<Null>



City of Fairhope - Outfall Inventory Point Clear Creek Watershed


PCC-243166-B

PCC-243166-B




IMG_0035492.jpg

COF MS4 ID	PCC-243166-B
Watershed	Point Clear Creek
Material	Earthen
Shape_1	Trapezoid
Depth	3
Top Width	12
Bottom Width	6
Type	Open Drainage
Category	Private
Outfall_No	<Null>
Comment	Private retention discharge
Flow Description	
Outfall Damage	
Deposits/Stains	
Abnormal Vegetation	Excessive
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	
Diameter	0
Submerged in Water	
Submerged With Sediment	
Date Collected	7/27/2012
2012 Photo 1	0035492
2012 Photo 2	<Null>



City of Fairhope – Outfall Inventory Point Clear Creek Watershed

PCC-2432-A




IMG_0042566.jpg

COF MS4 ID	PCC-2432-A
Watershed	Point Clear Creek
Material	Earthen
Shape_1	Trapezoid
Depth	3
Top Width	8
Bottom Width	1
Type	Open Drainage
Category	
Outfall_No	<Null>
Comment	Ditch head south
Flow Description	None
Outfall Damage	
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	0
Diameter	0
Submerged in Water	0
Submerged With Sediment	0
Date Collected	8/22/2012
2012 Photo 1	0042566
2012 Photo 2	<Null>

City of Fairhope - Outfall Inventory Point Clear Creek Watershed


PCC-267180-A ✕

PCC-267180-A



IMG_0036525.jpg


COF MS4 ID	PCC-267180-A
Watershed	Point Clear Creek
Material	HDPE
Shape_1	Circular
Depth	0
Top Width	0
Bottom Width	0
Type	Closed Pipe
Category	
Outfall_No	<Null>
Comment	Road discharge to private retention
Flow Description	
Outfall Damage	
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	1
Diameter	36
Submerged in Water	No
Submerged With Sediment	No
Date Collected	8/8/2012
2012 Photo 1	0036525
2012 Photo 2	<Null>



City of Fairhope - Outfall Inventory Point Clear Creek Watershed

PCC-267180-B

PCC-267180-B




IMG_0036522.jpg

COF MS4 ID	PCC-267180-B
Watershed	Point Clear Creek
Material	Rip_rap
Shape_1	Trapezoid
Depth	4
Top Width	15
Bottom Width	3
Type	Open Drainage
Category	
Outfall_No	<Null>
Comment	From road discharge below pipe discharge
Flow Description	None
Outfall Damage	
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	0
Diameter	0
Submerged in Water	0
Submerged With Sediment	0
Date Collected	8/8/2012
2012 Photo 1	0036522
2012 Photo 2	<Null>

City of Fairhope - Outfall Inventory Point Clear Creek Watershed

PCC-267180-C

PCC-267180-C



IMG_0036521.jpg


COF MS4 ID	PCC-267180-C
Watershed	Point Clear Creek
Material	HDPE
Shape_1	Circular
Depth	0
Top Width	0
Bottom Width	0
Type	Closed Pipe
Category	
Outfall_No	<Null>
Comment	From road
Flow Description	None
Outfall Damage	
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	1
Diameter	30
Submerged in Water	No
Submerged With Sediment	Partially
Date Collected	8/8/2012
2012 Photo 1	0036521
2012 Photo 2	<Null>



City of Fairhope – Outfall Inventory Point Clear Creek Watershed

PCC-267180-D ✖


PCC-267180-D



IMG_0036523.jpg

[IMG_0036523.jpg](#) [IMG_0037524.jpg](#)

COF MS4 ID	PCC-267180-D
Watershed	Point Clear Creek
Material	Concrete
Shape_1	Other
Depth	2
Top Width	20
Bottom Width	20
Type	Open Drainage
Category	Private
Outfall_No	<Null>
Comment	Concrete private retention discharge
Flow Description	None
Outfall Damage	
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	0
Diameter	0
Submerged in Water	0
Submerged With Sediment	0
Date Collected	8/8/2012
2012 Photo 1	0036523
2012 Photo 2	0037524



City of Fairhope - Outfall Inventory Point Clear Creek Watershed

PCC-288984-A

PCC-288984-A


IMG_0041554.jpg

COF MS4 ID	PCC-288984-A
Watershed	Point Clear Creek
Material	Earthen
Shape_1	Other
Depth	0
Top Width	0
Bottom Width	0
Type	Open Drainage
Category	Private
Outfall_No	<Null>
Comment	Private retention
Flow Description	
Outfall Damage	
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	0
Diameter	0
Submerged in Water	0
Submerged With Sediment	0
Date Collected	8/8/2012
2012 Photo 1	0041554
2012 Photo 2	<Null>

City of Fairhope - Outfall Inventory Point Clear Creek Watershed


PCC-288984-B ✖

PCC-288984-B



IMG_0041555.jpg

COF MS4 ID	PCC-288984-B
Watershed	Point Clear Creek
Material	RCP
Shape_1	Circular
Depth	0
Top Width	0
Bottom Width	0
Type	Closed Pipe
Category	Private
Outfall_No	<Null>
Comment	Private retention discharge
Flow Description	None
Outfall Damage	
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	1
Diameter	24
Submerged in Water	No
Submerged With Sediment	No
Date Collected	8/8/2012
2012 Photo 1	0041555
2012 Photo 2	<Null>



City of Fairhope - Outfall Inventory Point Clear Creek Watershed


PCC-29244-A

PCC-29244-A

IMG_0036532.jpg


COF MS4 ID	PCC-29244-A
Watershed	Point Clear Creek
Material	Earthen
Shape_1	Other
Depth	0
Top Width	0
Bottom Width	0
Type	Open Drainage
Category	Private
Outfall_No	<Null>
Comment	Private retention
Flow Description	
Outfall Damage	
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	0
Diameter	0
Submerged in Water	0
Submerged With Sediment	0
Date Collected	8/8/2012
2012 Photo 1	0036532
2012 Photo 2	<Null>

City of Fairhope - Outfall Inventory Point Clear Creek Watershed



PCC-29244-B

PCC-29244-B



IMG_0036533.jpg

COF MS4 ID	PCC-29244-B
Watershed	Point Clear Creek
Material	Steel
Shape_1	Circular
Depth	0
Top Width	0
Bottom Width	0
Type	Closed Pipe
Category	Private
Outfall_No	<Null>
Comment	From private retention
Flow Description	Trickle
Outfall Damage	
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	1
Diameter	30
Submerged in Water	No
Submerged With Sediment	No
Date Collected	8/8/2012
2012 Photo 1	0036533
2012 Photo 2	<Null>

City of Fairhope - Outfall Inventory Point Clear Creek Watershed

PCC-29244-C

PCC-29244-C


IMG_0036531.jpg

COF MS4 ID	PCC-29244-C
Watershed	Point Clear Creek
Material	RCP
Shape_1	Circular
Depth	0
Top Width	0
Bottom Width	0
Type	Closed Pipe
Category	Private
Outfall_No	<Null>
Comment	Private retention discharge
Flow Description	None
Outfall Damage	
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	1
Diameter	42
Submerged in Water	Partially
Submerged With Sediment	No
Date Collected	8/8/2012
2012 Photo 1	0036531
2012 Photo 2	<Null>

City of Fairhope - Outfall Inventory Point Clear Creek Watershed


PCC-327695-A

PCC-327695-A



IMG_0036528.jpg

COF MS4 ID	PCC-327695-A
Watershed	Point Clear Creek
Material	Earthen
Shape_1	Other
Depth	1
Top Width	12
Bottom Width	10
Type	Open Drainage
Category	
Outfall_No	<Null>
Comment	Discharge from road
Flow Description	
Outfall Damage	
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	0
Diameter	0
Submerged in Water	0
Submerged With Sediment	0
Date Collected	8/8/2012
2012 Photo 1	0036528
2012 Photo 2	<Null>



BARTLETT AV
MUSKET AV
SILVERSMITH ST
CRAFTSMAN AV

City of Fairhope - Outfall Inventory Point Clear Creek Watershed

PCC-327695-B

PCC-327695-B

IMG_0036529.jpg

COF MS4 ID	PCC-327695-B
Watershed	Point Clear Creek
Material	Earthen
Shape_1	Other
Depth	0
Top Width	0
Bottom Width	0
Type	Open Drainage
Category	Private
Outfall_No	<Null>
Comment	Private retention
Flow Description	
Outfall Damage	
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	0
Diameter	0
Submerged in Water	0
Submerged With Sediment	0
Date Collected	8/8/2012
2012 Photo 1	0036529
2012 Photo 2	<Null>

City of Fairhope - Outfall Inventory Point Clear Creek Watershed

PCC-327695-C

PCC-327695-C



IMG_0036530.jpg

COF MS4 ID	PCC-327695-C
Watershed	Point Clear Creek
Material	Concrete
Shape_1	Other
Depth	2
Top Width	5
Bottom Width	5
Type	Open Drainage
Category	Private
Outfall_No	<Null>
Comment	Private retention discharge
Flow Description	None
Outfall Damage	
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	0
Diameter	0
Submerged in Water	0
Submerged With Sediment	0
Date Collected	8/8/2012
2012 Photo 1	0036530
2012 Photo 2	<Null>



City of Fairhope - Outfall Inventory Point Clear Creek Watershed

PCC-327698-A

IMG_0036526.jpg

COF MS4 ID	PCC-327698-A
Watershed	Point Clear Creek
Material	Concrete
Shape_1	Other
Depth	2
Top Width	6
Bottom Width	6
Type	Open Drainage
Category	Private
Outfall_No	<Null>
Comment	Private retention discharge structure
Flow Description	None
Outfall Damage	
Deposits/Stains	
Abnormal Vegetation	Excessive
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	0
Diameter	0
Submerged in Water	0
Submerged With Sediment	0
Date Collected	8/8/2012
2012 Photo 1	0036526
2012 Photo 2	<Null>

City of Fairhope - Outfall Inventory Point Clear Creek Watershed

PCC-327698-B

PCC-327698-B

IMG_0036527.jpg

COF MS4 ID	PCC-327698-B
Watershed	Point Clear Creek
Material	Earthen
Shape_1	Other
Depth	0
Top Width	0
Bottom Width	0
Type	Open Drainage
Category	Private
Outfall_No	<Null>
Comment	Private retention pond
Flow Description	
Outfall Damage	
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	0
Diameter	0
Submerged in Water	0
Submerged With Sediment	0
Date Collected	8/8/2012
2012 Photo 1	0036527
2012 Photo 2	<Null>

City of Fairhope - Outfall Inventory Point Clear Creek Watershed

PCC-6614-A ✖

PCC-6614-A



IMG_0036534.jpg

[IMG_0036534.jpg](#) [IMG_0037535.jpg](#)

COF MS4 ID	PCC-6614-A
Watershed	Point Clear Creek
Material	Earthen
Shape_1	Other
Depth	0
Top Width	0
Bottom Width	0
Type	Open Drainage
Category	Private
Outfall_No	<Null>
Comment	Private retention
Flow Description	None
Outfall Damage	
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	0
Diameter	0
Submerged in Water	0
Submerged With Sediment	0
Date Collected	8/8/2012
2012 Photo 1	0036534
2012 Photo 2	0037535

