



City of Fairhope - Outfall Inventory Turkey Branch Watershed



The image displays an aerial photograph of the Turkey Branch Watershed. A callout window is overlaid on the left side, providing details for a specific outfall. The callout window includes a photo of the outfall and a table of metadata. The photo shows a pipe opening in a grassy area. The metadata table lists various attributes such as COF MS4 ID, Watershed, Material, Shape, Depth, Top Width, Bottom Width, Type, Category, Outfall No, Comment, Flow Description, Outfall Damage, Deposits/Stains, Abnormal Vegetation, Poor Pool Quality, Pipe Benthic Growth, Barrels, Diameter, Submerged in Water, Submerged With Sediment, Date Collected, 2012 Photo 1, and 2012 Photo 2.


TB-257064-A	
COF MS4 ID	TB-257064-A
Watershed	Turkey Branch
Material	RCP
Shape_1	Arch
Depth	<Null>
Top Width	<Null>
Bottom Width	<Null>
Type	Closed Pipe
Category	
Outfall_No	<Null>
Comment	37x23 arch under Bishop
Flow Description	None
Outfall Damage	
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	1
Diameter	37
Submerged in Water	No
Submerged With Sediment	No
Date Collected	8/8/2012
2012 Photo 1	0035499
2012 Photo 2	<Null>

City of Fairhope - Outfall Inventory Turkey Branch Watershed



TB-257064-B x3

TB-257064-B



IMG_0035498.jpg

COF MS4 ID	TB-257064-B
Watershed	Turkey Branch
Material	RCP
Shape_1	Arch
Depth	<Null>
Top Width	<Null>
Bottom Width	<Null>
Type	Closed Pipe
Category	
Outfall_No	<Null>
Comment	37x23 arch under Bishop
Flow Description	None
Outfall Damage	
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	1
Diameter	37
Submerged in Water	No
Submerged With Sediment	No
Date Collected	8/8/2012
2012 Photo 1	0035498
2012 Photo 2	<Null>

City of Fairhope - Outfall Inventory Turkey Branch Watershed

TB-309518-A

TB-309518-A

IMG_0035496.jpg

[IMG_0035496.jpg](#) [IMG_0036497.jpg](#)

COF MS4 ID	TB-309518-A
Watershed	Turkey Branch
Material	CMP
Shape_1	Circular
Depth	<Null>
Top Width	<Null>
Bottom Width	<Null>
Type	Closed Pipe
Category	
Outfall_No	<Null>
Comment	Under Bishop Road
Flow Description	None
Outfall Damage	
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	1
Diameter	36
Submerged in Water	No
Submerged With Sediment	Partially
Date Collected	8/8/2012
2012 Photo 1	0035496
2012 Photo 2	0036497

City of Fairhope - Outfall Inventory Turkey Branch Watershed

TB-309518-B

TB-309518-B

IMG_0035495.jpg

COF MS4 ID	TB-309518-B
Watershed	Turkey Branch
Material	CMP
Shape_1	Circular
Depth	<Null>
Top Width	<Null>
Bottom Width	<Null>
Type	Closed Pipe
Category	
Outfall_No	<Null>
Comment	Under Bishop Road
Flow Description	None
Outfall Damage	Crushed
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	1
Diameter	24
Submerged in Water	No
Submerged With Sediment	Partially
Date Collected	8/8/2012
2012 Photo 1	0035495
2012 Photo 2	<Null>