

City of Fairhope - Outfall Inventory Waterhole Branch Watershed



WB-12786-A

WB-12786-A




IMG_0041544.jpg

[IMG_0041544.jpg](#) [IMG_0042545.jpg](#)


COF MS4 ID	WB-12786-A
Watershed	Waterhole Branch
Material	Concrete
Shape_1	Trapezoid
Depth	1
Top Width	12
Bottom Width	5
Type	Open Drainage
Category	
Outfall_No	<Null>
Comment	From airport taxiway
Flow Description	None
Outfall Damage	
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	0
Diameter	0
Submerged in Water	0
Submerged With Sediment	0
Date Collected	8/8/2012
2012 Photo 1	0041544
2012 Photo 2	0042545

City of Fairhope - Outfall Inventory Waterhole Branch Watershed



WB-226620-A

WB-226620-A



IMG_0036536.jpg


[IMG_0036536.jpg](#) | [IMG_0038537.jpg](#)

COF MS4 ID	WB-226620-A
Watershed	Waterhole Branch
Material	RCP
Shape_1	Circular
Depth	<Null>
Top Width	<Null>
Bottom Width	<Null>
Type	Closed Pipe
Category	
Outfall_No	<Null>
Comment	5' drop off pipe discharge in hole.
Flow Description	None
Outfall Damage	
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	1
Diameter	18
Submerged in Water	No
Submerged With Sediment	No
Date Collected	8/8/2012
2012 Photo 1	0036536
2012 Photo 2	0038537

City of Fairhope – Outfall Inventory Waterhole Branch Watershed

WB-226620-B


WB-226620-B




IMG_0040541.jpg

COF MS4 ID	WB-226620-B
Watershed	Waterhole Branch
Material	RCP
Shape_1	Circular
Depth	<Null>
Top Width	<Null>
Bottom Width	<Null>
Type	Closed Pipe
Category	
Outfall_No	<Null>
Comment	From road at airport
Flow Description	None
Outfall Damage	Spalling_Cracking_Ch
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	1
Diameter	15
Submerged in Water	No
Submerged With Sediment	No
Date Collected	8/8/2012
2012 Photo 1	0040541
2012 Photo 2	<Null>

City of Fairhope - Outfall Inventory Waterhole Branch Watershed


WB-226620-C	
WB-226620-C	
	
IMG_0040540.jpg	
COF MS4 ID	WB-226620-C
Watershed	Waterhole Branch
Material	RCP
Shape_1	Circular
Depth	<Null>
Top Width	<Null>
Bottom Width	<Null>
Type	Closed Pipe
Category	
Outfall_No	<Null>
Comment	From road at airport
Flow Description	None
Outfall Damage	Spalling_Cracking_Ch
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	1
Diameter	18
Submerged in Water	
Submerged With Sediment	No
Date Collected	8/8/2012
2012 Photo 1	0040540
2012 Photo 2	<Null>

City of Fairhope - Outfall Inventory Waterhole Branch Watershed



WB-226620-D


WB-226620-D



IMG_0040542.jpg

COF MS4 ID	WB-226620-D
Watershed	Waterhole Branch
Material	HDPE
Shape_1	Circular
Depth	<Null>
Top Width	<Null>
Bottom Width	<Null>
Type	Closed Pipe
Category	
Outfall_No	<Null>
Comment	Roof drainage
Flow Description	None
Outfall Damage	
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	1
Diameter	12
Submerged in Water	No
Submerged With Sediment	No
Date Collected	8/8/2012
2012 Photo 1	0040542
2012 Photo 2	<Null>

City of Fairhope - Outfall Inventory Waterhole Branch Watershed



WB-226620-E

WB-226620-E

IMG_0041543.jpg

COF MS4 ID	WB-226620-E
Watershed	Waterhole Branch
Material	RCP
Shape_1	Circular
Depth	<Null>
Top Width	<Null>
Bottom Width	<Null>
Type	Closed Pipe
Category	
Outfall_No	<Null>
Comment	From road at airport
Flow Description	None
Outfall Damage	
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	1
Diameter	15
Submerged in Water	No
Submerged With Sediment	No
Date Collected	8/8/2012
2012 Photo 1	0041543
2012 Photo 2	<Null>

City of Fairhope - Outfall Inventory Waterhole Branch Watershed

WB-226621-A

WB-226621-A



IMG_0038538.jpg

COF MS4 ID	WB-226621-A
Watershed	Waterhole Branch
Material	RCP
Shape_1	Circular
Depth	<Null>
Top Width	<Null>
Bottom Width	<Null>
Type	Closed Pipe
Category	
Outfall_No	<Null>
Comment	Fresh sediment
Flow Description	None
Outfall Damage	
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	1
Diameter	18
Submerged in Water	Partially
Submerged With Sediment	Partially
Date Collected	8/8/2012
2012 Photo 1	0038538
2012 Photo 2	<Null>



City of Fairhope - Outfall Inventory Waterhole Branch Watershed



WB-226621-B

WB-226621-B



IMG_0039539.jpg


COF MS4 ID	WB-226621-B
Watershed	Waterhole Branch
Material	RCP
Shape_1	Circular
Depth	<Null>
Top Width	<Null>
Bottom Width	<Null>
Type	Closed Pipe
Category	
Outfall_No	<Null>
Comment	From airport
Flow Description	None
Outfall Damage	
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	1
Diameter	18
Submerged in Water	No
Submerged With Sediment	Partially
Date Collected	8/8/2012
2012 Photo 1	0039539
2012 Photo 2	<Null>

City of Fairhope - Outfall Inventory Waterhole Branch Watershed



WB-226622-A


WB-226622-A



IMG_0041546.jpg

COF MS4 ID	WB-226622-A
Watershed	Waterhole Branch
Material	Concrete
Shape_1	Trapezoid
Depth	1
Top Width	8
Bottom Width	3
Type	Open Drainage
Category	
Outfall_No	<Null>
Comment	Flume from airport
Flow Description	
Outfall Damage	
Deposits/Stains	
Abnormal Vegetation	Excessive
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	0
Diameter	0
Submerged in Water	0
Submerged With Sediment	0
Date Collected	8/8/2012
2012 Photo 1	0041546
2012 Photo 2	<Null>

City of Fairhope - Outfall Inventory Waterhole Branch Watershed



The image shows an aerial view of a drainage ditch and a pond. A data overlay window is positioned on the left side of the image, providing details for a specific outfall. The window includes a thumbnail image of the outfall, a table of attributes, and a vertical label 'GRACE LAKE DR' on the right edge of the aerial photo.


WB-226623-A	
COF MS4 ID	WB-226623-A
Watershed	Waterhole Branch
Material	Rip_rap
Shape_1	Trapezoid
Depth	3
Top Width	20
Bottom Width	6
Type	Open Drainage
Category	
Outfall_No	<Null>
Comment	Runway drainage ditch
Flow Description	None
Outfall Damage	
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	0
Diameter	0
Submerged in Water	0
Submerged With Sediment	0
Date Collected	8/8/2012
2012 Photo 1	0041547
2012 Photo 2	<Null>

GRACE LAKE DR

City of Fairhope - Outfall Inventory Waterhole Branch Watershed

WB-226623-B x


WB-226623-B




IMG_0041548.jpg

[IMG_0041548.jpg](#) [IMG_0042549.jpg](#)

COF MS4 ID	WB-226623-B
Watershed	Waterhole Branch
Material	RCP
Shape_1	Box
Depth	<Null>
Top Width	<Null>
Bottom Width	<Null>
Type	Closed Pipe
Category	
Outfall_No	<Null>
Comment	4x6 box under runway stilling basin downstream
Flow Description	None
Outfall Damage	
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	2
Diameter	72
Submerged in Water	No
Submerged With Sediment	No
Date Collected	8/8/2012
2012 Photo 1	0041548
2012 Photo 2	0042549



City of Fairhope - Outfall Inventory Waterhole Branch Watershed



WB-226623-C

WB-226623-C


IMG_0041552.jpg

[IMG_0041552.jpg](#) [IMG_0042553.jpg](#)

COF MS4 ID	WB-226623-C
Watershed	Waterhole Branch
Material	Rip_rap
Shape_1	Trapezoid
Depth	3
Top Width	20
Bottom Width	6
Type	Open Drainage
Category	
Outfall_No	<Null>
Comment	Runway drainage ditch
Flow Description	None
Outfall Damage	
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	0
Diameter	0
Submerged in Water	0
Submerged With Sediment	
Date Collected	8/8/2012
2012 Photo 1	0041552
2012 Photo 2	0042553

City of Fairhope - Outfall Inventory Waterhole Branch Watershed

WB-243146-A




IMG_0035490.jpg

COF MS4 ID	WB-243146-A
Watershed	Waterhole Branch
Material	Earthen
Shape_1	Other
Depth	0
Top Width	0
Bottom Width	0
Type	Open Drainage
Category	Private
Outfall_No	<Null>
Comment	Private retention pond
Flow Description	
Outfall Damage	
Deposits/Stains	
Abnormal Vegetation	Excessive
Poor Pool Quality	Excessive_Alg
Pipe Benthic Growth	
Barrels	
Diameter	0
Submerged in Water	
Submerged With Sediment	
Date Collected	7/27/2012
2012 Photo 1	0035490
2012 Photo 2	<Null>

City of Fairhope - Outfall Inventory Waterhole Branch Watershed

WB-243149-A

WB-243149-A




IMG_0035489.jpg

COF MS4 ID	WB-243149-A
Watershed	Waterhole Branch
Material	Earthen
Shape_1	Other
Depth	0
Top Width	0
Bottom Width	0
Type	Open Drainage
Category	Private
Outfall_No	<Null>
Comment	Private retention pond
Flow Description	
Outfall Damage	
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	
Diameter	0
Submerged in Water	
Submerged With Sediment	
Date Collected	7/27/2012
2012 Photo 1	0035489
2012 Photo 2	<Null>

City of Fairhope - Outfall Inventory Waterhole Branch Watershed

WB-2496-A 23


WB-2496-A



IMG_0035493.jpg

[IMG_0035493.jpg](#) | [IMG_0036494.jpg](#)

COF MS4 ID	WB-2496-A
Watershed	Waterhole Branch
Material	Earthen
Shape_1	Other
Depth	3
Top Width	20
Bottom Width	5
Type	Open Drainage
Category	
Outfall_No	<Null>
Comment	Waterhole Branch crossing with road
Flow Description	None
Outfall Damage	
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	0
Diameter	0
Submerged in Water	0
Submerged With Sediment	
Date Collected	8/8/2012
2012 Photo 1	0035493
2012 Photo 2	0036494



COUNTY RD 13

GRACE LAKE DR

City of Fairhope - Outfall Inventory Waterhole Branch Watershed

WB-251558-A

WB-251558-A

IMG_0041550.jpg

COF MS4 ID	WB-251558-A
Watershed	Waterhole Branch
Material	Earthen
Shape_1	Trapezoid
Depth	1
Top Width	20
Bottom Width	2
Type	Open Drainage
Category	
Outfall_No	<Null>
Comment	Discharge from airport
Flow Description	None
Outfall Damage	
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	0
Diameter	0
Submerged in Water	0
Submerged With Sediment	
Date Collected	8/8/2012
2012 Photo 1	0041550
2012 Photo 2	<Null>

City of Fairhope - Outfall Inventory Waterhole Branch Watershed

WB-251558-B

WB-251558-B

IMG_0041551.jpg

COF MS4 ID	WB-251558-B
Watershed	Waterhole Branch
Material	Earthen
Shape_1	Trapezoid
Depth	1
Top Width	6
Bottom Width	1
Type	Open Drainage
Category	
Outfall_No	<Null>
Comment	Discharge from airport
Flow Description	None
Outfall Damage	
Deposits/Stains	
Abnormal Vegetation	
Poor Pool Quality	
Pipe Benthic Growth	
Barrels	0
Diameter	0
Submerged in Water	0
Submerged With Sediment	0
Date Collected	8/8/2012
2012 Photo 1	0041551
2012 Photo 2	<Null>